DIRECT PLATING SYSTEM
DP PREDIP

INTRODUCTION:

DP Predip is designed to protect the precious palladium activator bath from any foreign substances that could be transferred to it by normal drag out, dripping or poor rinsing. And also, to promote activator adsorption on the conditioned through hole surface.

OPERATING DATA

1-BATH MAKE UP:

Use as supplied.

2-BATH MAINTENANCE:

Replenishment

For every 1 m^2 (total surface area) processed add 50 ml of DP Predip solution

Replacement

DP Predip bath should be totally replaced when total surface area of 20 m^2/L has been processed through the solution.

Yield

1 L of DP Predip solution is sufficient to process a total surface area of 18 m^2

UNITED INDUSTRIAL & ENGINEERING SERVICES Co.

3-Operating Parameters

Operating temperature	Room temperature.
Time	1 minute
Agitation	board movement is necessary.